



NARKOMED 6000 TECHNICAL SERVICE BULLETIN # 6013

Product:	Narkomed 6000
Date:	March 5, 2001
Re:	Software Enhancement 3.01 for Narkomed 6000's fitted with Integrated Patient Monitoring Module (IPMM).
Reference Doc:	Product Bulletin 130
Reason/Rational:	Software version 3.01 offers new features and functionality improvements that are required for all Narkomed 6000's configured with an IPMM.
Solution/ Procedure:	Refer to installation instructions provided in Field Service Procedure SP00236 Narkomed 6000 3.01 Enhancement
Devices affected:	10092, 10100, 10132, 10178, 10234, 10238, 10329, 10331, 10350, 10363, 10377, 10561-10570, 10590-10592, 10594, 10598, 10654-10678, 10682, 10684, 10685, 10688, 10689, 10692, 10739, 10741, 10764, 10765, 10771, 10775, 10776, 10786-10789, 10793, 10797-10800, 10806, 10807, 10819-10823, 10825, 10827, 10829, 10831, 10878, 10882, 10884, 10887, 10890, 10892, 10911, 10912, 10920-10922, 10928, 10933-10936, 10947, 10952, 10974, 10975, 10979, 11029, 11031, 11032, 11038, 11044, 11045, 11049, 11051-11058, 11071
	NOTE: All Distributor and Regional Service Managers will be provided with a report identifying the affected customers units in their territory.

Timing/When:	These updates shall be performed on included devices during the next Service Call or Manufacturer's Certification or be completed no later than September 30, 2002.																		
Additional Info:	If the 2.06 software and hardware modifications have not been performed, they will need to be completed prior to 3.01 installation.																		
Costs:	If you are the service provider of a machine serial number that is included in the list of affected devices the parts required for this modification are available at no charge if this TSB is referenced at the time the order is being placed. This modification will also be available at no charge if sufficient evidence that an IPMM after-market update kit has been installed.																		
Ordering Info/Parts:	<table><tr><td>1 ea.</td><td>*4115420-003</td><td>CD-ROM NM6000 SOFTWARE-V3.01</td></tr><tr><td>1 ea.</td><td>4114915-009</td><td>INSTRUCTION MAN NM6000-V3.01</td></tr><tr><td>1 ea.</td><td>4116574-003</td><td>INSTRUCTION MAN IPMM OPTION</td></tr><tr><td>1 ea.</td><td>SP00236</td><td>SP-SW V3.01 ENHANCEMENT NM6K</td></tr><tr><td>1 ea.</td><td>4117725</td><td>LABEL-SW 3.01 – NM6000</td></tr><tr><td>1 ea.</td><td>4117735</td><td>USER INFO 3.01 ENHANCEMENT</td></tr></table> <p>* Maximum order quantity 1 CD-ROM per Technician</p>	1 ea.	*4115420-003	CD-ROM NM6000 SOFTWARE-V3.01	1 ea.	4114915-009	INSTRUCTION MAN NM6000-V3.01	1 ea.	4116574-003	INSTRUCTION MAN IPMM OPTION	1 ea.	SP00236	SP-SW V3.01 ENHANCEMENT NM6K	1 ea.	4117725	LABEL-SW 3.01 – NM6000	1 ea.	4117735	USER INFO 3.01 ENHANCEMENT
1 ea.	*4115420-003	CD-ROM NM6000 SOFTWARE-V3.01																	
1 ea.	4114915-009	INSTRUCTION MAN NM6000-V3.01																	
1 ea.	4116574-003	INSTRUCTION MAN IPMM OPTION																	
1 ea.	SP00236	SP-SW V3.01 ENHANCEMENT NM6K																	
1 ea.	4117725	LABEL-SW 3.01 – NM6000																	
1 ea.	4117735	USER INFO 3.01 ENHANCEMENT																	
Distribution:	Draeger Medical Inc. USA – Service; Education, Customer Service, Affected DMI Distributors																		
If you have any questions, please contact Technical Support by phone at 1-800-543-5047, by fax at 1-215-721-5789 or by E-mail at techsupport@draegermed.com																			